

Service Bulletin

Issued: 10/June/2022

Page

Ref No: RAC-0109

1 / 2

Product: Ceiling type indoor unit

Model: Refer to model information below

Subject: Service part changeover for assembly efficiency improvement:
Gearbox sub assy

FUJITSU GENERAL LIMITED

3-3-17, Suenaga, Takatsu-ku, Kawasaki,
Kanagawa 213-8502, Japan

TEL: +81-44-861-7752

FAX: +81-44-861-7875


1. Overview

The part number of the Gearbox sub assy has been changed to improve the assembly efficiency from production after May 26, 2022. You can use a new part number Gearbox sub assy on the existing models. When you order a Gearbox sub assy with an old part number, you will receive one with a new part number.


Part	Part number	
	Old	New
Gearbox sub assy (including stepping motor)	9384312006	9384312013

Changes in the structure of the Gearbox sub assy (including stepping motor)

- The gear cover and the gearbox are fastened together to close the gear cover securely.
- A new hole in the center of the gear cover allows the state of the gear B assembly to be checked.



Fastening the cover and the box together with screws



2. Model information

Target model	Serial number	Applied date
ABYG18KRTA	T001421	27/May/2022
ABYG22KRTA	T000337	27/May/2022
ABYG24KRTA	T001211	27/May/2022
ABYG30KRTA	T000562	26/May/2022
ABYG36KRTA	T001159	26/May/2022
ABYG45KRTA	T001279	27/May/2022
ABYG54KRTA	T000963	27/May/2022
ABHG18KRTA	T000481	26/May/2022
ABHG22KRTA	T000128	30/May/2022
ABHG24KRTA	T000510	27/May/2022
ABHG30KRTA	T000280	26/May/2022
ABHG36KRTA	T000333	27/May/2022
ABHG45KRTA	T000399	27/May/2022
ABHG54KRTA	T000360	27/May/2022
RYG18KRTA	T000100	30/May/2022
RYG22KRTA	T000040	TBD
RYG24KRTA	T000079	27/May/2022
RYG30KRTA	T000033	TBD
RYG36KRTA	T000064	27/May/2022
RYG45KRTA	T000079	27/May/2022
RYG54KRTA	T000045	27/May/2022
ABBH18KRTA	T000035	TBD
ABBH24KRTA	T000039	TBD
ABBH30KRTA	T000020	TBD
ABBH36KRTA	T000104	TBD
ABBH45KRTA	T000116	TBD
ABBH54KRTA	T000001	TBD